

HIGH PRESSURE COUPLERS AND FITTINGS

- ▶ Suitable for working pressures up to 700 bar
- ▶ Designed to ensure easy system connection and assembly

| Model | | | |
|--------|-------------|--|--|
| number | See picture | Description | Thread specification |
| HF7 | 1 | Nipple | 1/4" NPT male to 1/4" NPT male |
| HF8 | 5 | Adaptor | 1/4" NPT female to 1/4" NPT female |
| HF10 | 2 | Elbow | % " NPT female to $%$ " NPT female |
| HF12 | 3 | Equal tee | %" NPT female |
| HF13 | 4 | Cross | %" NPT female |
| HF14 | 5 | Adaptor | %" NPT female to $%$ " NPT female |
| HF15 | 5 | Reducer | $\%$ " NPT female to $1\!\!4$ " NPT female |
| HF16 | 6 | Elbow | %" NPT female to %" NPT male |
| HF17 | 1 | Nipple | % " NPT male to $%$ " NPT male |
| HF19 | 1 | Long nipple | %" NPT male to %" NPT male |
| HF24 | 7 | Adaptor | %" NPT male to %" BSP female |
| HF27 | 1 | Nipple | 1/4" NPT male to 3%" NPT male |
| HF30 | 7 | Reducer | 3%" NPT male to 1/4" NPT female |
| HF31 | 8 | Tee | %" NPT female to %" NPT male |
| HF33 | 7 | Reducer | %" NPT male to ¼" BSP female |
| HF55 | 7 | Reducer | %" NPT female to $%$ " NPT male |
| HF69 | 7 | Adaptor | ½" BSP male to ¾" NPT female |
| CF1 | 9 | Female coupler | %" NPT male |
| СМ1 | 10 | Male coupler | ⅓" NPT female |
| CMF1 | 9 + 10 | Complete coupler | %" NPT |
| CF2 | 9 | Female coupler | 1/4" NPT male |
| СМ2 | 10 | Male coupler | 1/4" NPT female |
| CMF2 | 9 + 10 | Complete coupler | 1/4" NPT |
| CFD1 | 11 | Metal dust cap for CF1 | |
| CMD1 | 12 | Metal dust cap for CM1 | |
| CFD2 | 11 | Metal dust cap for CF2 | |
| CMD2 | 12 | Metal dust cap for CM2 | |
| PPC1 | 13 | Moulded universal dust cap to suit CF1 & CM1 | |
| | | p | |



Picture 1



Picture 2



Picture 3



Picture 4



Picture 5



Picture 6



Picture 7



Picture 8



Picture 9



Picture 10



Picture 11



Picture 12



Picture 13